Harrison Home Inspections Property Inspection Report



Your Address Here, Baltimore, MD 21224 Inspection prepared for: Your Name Here Real Estate Agent: -

Date of Inspection: 8/11/2022 Time: 4:30 PM Age of Home: 1963 Size: 2007

Inspector: Patrick Harrison

32845 10316 Greentop Rd, Cockeysville, 21030 Phone: 443-683-2228 Email: harrisoninspectionservices@gmail.com



Table Of Contents

Report Summary	2-6
Inspection Details	7
Grounds	8-12
Exterior Areas	13-15
Roof	16-17
Electrical	18-20
Heat/AC	21-25
Water Heater	26-28
Bathrooms	29-36
Bedrooms	37-41
Interior Areas	42-48
Kitchen	49-52
Laundry	53-56
Attic	57-60
Garage	61-64
Basement	65-74
Glossary	

Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all pages of the report as the summary alone does not explain all of the issues. All repairs should be done by a licensed & bonded tradesman or qualified professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

Grounds					
Page 8 Item: 1	Driveway and Walkway Condition	• There are numerous areas of damaged concrete surfaces. Recommend a concrete specialist provide an estimate for repair and or replacing.			
Page 9 Item: 3	Vegetation Observations	Trees within 6 feet foundation. Monitor for potential root damage.			
Page 10 Item: 5	Stairs & Handrail	 Loose guardrails observed. Secure as necessary 			
Exterior Areas					
Page 13 Item: 1	Doors	 Wood deterioration observed. Suggest repairs/replacement as needed. 			
Page 13 Item: 3	Siding Condition	• Siding-Soil contact or proximity. This may provide entrance of moisture or insects to siding. Recommend grading soil so there is at least 6" of space (where practical) between the siding and the soil below and checking for any damaged trim and siding materials.			
Roof					
Page 16 Item: 1	Roof Condition	 Some shingles damaged. Due to the conditions of the roof covering, we recommend evaluation by a professional roofing contractor for repair and certification as necessary. 			
Page 17 Item: 3	Chimney	• Chimney Crown shows signs of deterioration. Recommend having repaired by a qualified chimney contractor as necessary.			

Page 18 Item: 1 E	Electrical Panel	Double tapped breaker(s) inside panel box (more than one
		 electrical conductor attached). This is not standard practice, and may cause overheating or even an electrical fire. Recommend evaluation by an electrician. There is a Federal Pacific Electric service panel in the house. There are studies that show that some FPE circuit breakers are prone to problems that can lead to failures, lack of proper protection of circuits and other serious issues, including fire and electrocution. Although the Consumer Products Safety Commission has not issued a formal product recall, the panel is old and the company is now out of business. We cannot definitively call this panel defective, but recommend, for your peace of mind, to consult a qualified electrical contractor to get their opinion on this matter. You can learn more about this issue at: www.inspect-ny.com/fpe/fpepanel.htm Aluminum wiring present—Between 1965 and 1973, aluminum wiring was sometimes substituted for copper wiring in residential electrical systems. Connections in outlets, switches, and light fixtures with aluminum wiring become increasingly dangerous as time passes. Poor connections cause wiring to spark and overheat, creating a potential fire hazard. The wiring should be evaluated by a qualified electrician experienced in evaluating and correcting aluminum wiring), oxidation (caused when electric currents pass through wiring), oxidation (caused by exposure to oxygen in the air), and galvanic corrosion (caused when two different metals are connected together), all of which can cause poor connections. When wires are poorly connected they overheat, which creates a potential fire hazard.
Page 20 Item: 4 B	Breakers	• Stab-Lok breakers noted. Recommend review by a licensed electrician
Heat/AC		
Page 21 Item: 1 H	leater Condition	• Fuel Furnace: Last service date is over one year ago, or is unable to be determined. There are areas which cannot be seen without specialized equipment and training. One such area is the combustion chamber / heat exchanger where cold air blows across the "fire box", becoming the hot air that circulates throughout your home. During the life span of any furnace, this metal wall may develop a crack or a broken weld, allowing carbon monoxide to circulate throughout the home. This is why furnace specialists recommend a complete inspection annually; recommend having unit inspected by certified HVAC technician.
Page 22 Item: 3 E	Enclosure	Condensation leak observed near sump pump. Recommend review for repair as necessary
	AC Compress Condition	• With no recent service records observed, we recommend evaluation and service by a licensed HVAC contractor.

Water Heater		
Page 27 Item: 5	Water Heater Condition	• The water heater has exceeded its designed life expectancy. We make no warranty, guarantee or estimation as to the remaining useful life of this unit. Recommend budgeting for replacement.
Bathrooms	-	
Page 31 Item: 3	Ceiling Condition	 Biological growth present in some areas. Recommend having cleaned and treated as necessary.
Page 32 Item: 5	Electrical	• Outlets noted appear to have loose contacts. Recommend replacement by a licensed electrician.
Page 33 Item: 9	Counters	• The counter tops appear to be loose on the cabinet. Recommend having secured as necessary
Page 33 Item: 10	Exhaust Fan	• The fan terminates improperly in the attic. This can create excessive moisture. Recommend directing the vent towards the exterior to allow for proper ventilation.
Page 34 Item: 14	Plumbing	 Unprofessional repair observed at time of inspection. Recommend review by licensed plumber for repair as necessary
Page 34 Item: 16	Shower Walls	 Missing/damaged caulking/grout observed, recommend repair as necessary.
Page 35 Item: 20	Toilets	• The toilet bowl is loose at floor anchor bolts. The wax ring inside the unit must have a snug, secure fit in order to keep from leaking. Properly resealing and re-securing this unit is suggested to prevent water leakage and damage to the sub- floor area. This type of damage is not always visible or accessible to the inspector at time of inspection.
Bedrooms		
Page 40 Item: 5	Electrical	 Some loose receptacles were found, they should be installed correctly by a licensed electrician. Hot-neutral reversed (reversed polarity) outlets present. Recommend repair as necessary by a licensed electrician
Interior Areas	•	
Page 46 Item: 9	Smoke Detectors	 Old detectors. Smoke detectors should be replaced every 10 years. Recommend replacing as necessary NOTICE: There are missing CO (Carbon Monoxide) detector(s) noted. The Consumer Product Safety Commission recommends that every residence with fuel- burning (gas) appliances be equipped with a UL Listed CO alarm. CO is colorless and odorless and thus impossible to detect without a proper electronic detector. At a minimum, put an alarm near the sleeping rooms on each level in your home. For the most trouble-free operation, I recommend the plug-in type not the battery operated type with digital readout that tells you the peak CO concentration whenever you push the peak level button.
Page 47 Item: 10	Stairs & Handrail	Loose handrail noted. Recommend repair.
Page 47 Item: 11	Patio Doors	• Interior keyed deadbolt observed. This is a safety concern in the event of an emergency. Recommend replacing with a latched deadbolt for safety.

Kitchen					
Page 50 Item: 4	Electrical	Hot-neutral reversed (reversed polarity) outlets present.			
		Recommend repair as necessary by a licensed electrician			
Page 50 Item: 5	GFCI	 No GFCI protection present, suggest installing GFCI protected receptacles for safety. 			
Laundry					
Page 54 Item: 5	Electrical	Outlets noted appear to have loose contacts. Recommend replacement by a licensed electrician.			
Page 55 Item: 14	Plumbing	Active faucet leak observed. Recommend repair by a licensed plumber			
Attic					
Page 58 Item: 4	Ventilation	Attic fan is inoperable, recommend review for repair.			
Page 58 Item: 6	Electrical	 Connections made outside of a Junction Box, which is a potential shock or electrocution hazard. Wire ends are outside of a Junction Box, which is a potential shock or electrocution hazard. Recommend repair by a licensed electrician Unprofessional installation of electrical wiring noted in attic. All wiring should be properly secured to the framing. Improper wiring observed at time of inspection. Recommend repair by licensed electrician for repair as necessary. 			
Garage		neeeeery.			
Page 61 Item: 1	Walls	Biological growth observed. Recommend cleaning and treating as necessary			
Page 63 Item: 7	Fire Door	 There is no self-closing device on the door from the house leading to the garage. It is strongly recommended that one be installed in order to protect the residence against garage originated fires. The door between the garage & house does not appear to be a fire rated door. This may not have been required when originally built. Fire doors are fundamental to the integrity of fire barriers which provide resistance to the spread of fire, smoke, and toxic gasses. This means that should a fire occur in the garage, this door does not afford protection until fire-rescue people arrive. This door should be replaced with a fire rated door. 			
Page 63 Item: 12	Cabinets	• Cabinets are not secured to the wall at time of inspection. Recommend review for repair as necessary			
Page 64 Item: 13	Counters	 Countertop is loose at cabinets in one or more locations. Recommend repair as necessary 			
Basement	· · · · · · · · · · · · · · · · · · ·				
Page 65 Item: 1	Foundation/Walls	• There were signs of water penetration at foundation wall. Recommend conferring with seller as to any past moisture problems and have evaluated by a qualified basement waterproofing specialist.			
L					

Page 68 Item: 6	Plumbing	 Unprofessional repair noted at one or more locations noted, recommend review and repairs by a Qualified Plumber. Cast iron drain lines have a life expectancy of 60-75 years. Recommend budgeting for replacement, BEFORE leaks occur.
Page 69 Item: 9	Basement Electric	 Connections made outside of a Junction Box, which is a potential shock or electrocution hazard. Recommend installing proper junction boxes. Improper wiring observed at one or more locations. Recommend review by a licensed electrician for repair as necessary
Page 71 Item: 17	Framing	 Visible evidence of Wood Destroying Insects observed. Recommend obtaining a pest inspection to confirm that no active infestation exists. Damage from what appears to be caused by Wood Destroying insects is noted, Recommend review of support structure by a licensed contractor and have WDI inspection performed to be sure no active infestation is present.
Page 71 Item: 18	Subfloor	 Biological growth present in some areas. Recommend having cleaned and treated as necessary.
Page 72 Item: 19	Columns	• Steel column top flanges are not spot welded or bolted to the steel beams.
Page 73 Item: 20	Basement/Crawlsp ace Ductwork	• Biological growth observed on ductwork surface in one or more locations. Recommend having areas cleaned and treated as necessary
Page 74 Item: 21	Smoke Detectors	 Old detectors. Smoke detectors should be replaced every 10 years. Recommend replacing as necessary NOTICE: There was no visible CO (Carbon Monoxide) detector(s) in the home. The Consumer Product Safety Commission recommends that every residence with fuel- burning (gas) appliances be equipped with a UL Listed CO alarm. CO is colorless and odorless and thus impossible to detect without a proper electronic detector. At a minimum, put an alarm near the sleeping rooms on each level in your home. For the most trouble-free operation, I recommend the plug-in type not the battery operated type with digital readout that tells you the peak CO concentration whenever you push the peak level button.

Inspection Details

1. Attendance	
	In Attendance: Client present • Buyer Agent present
2. Home Type	
	Home Type: Single Family Home
3. Occupancy	
	Occupancy: Vacant - Furnished • The utilities were on at the time of inspection. • Access to some items such as: electrical outlets/receptacles, windows, wall/floor surfaces, and cabinet interiors may be restricted by furniture or personal belongings. Any such items are excluded from this inspection report.
4. Temperature	
	86 degrees
5. Weather	
	Suny

Grounds	
Driveway and Walkway Condition	d. Os a susta sidena lla a stad
X None Materials: Concrete driveway noted X	d. • Concrete sidewalk noted.
	maged concrete surfaces. Recommend a
concrete specialist provide an estir	mate for repair and or replacing.
	Hanni -
and the second sec	
Cracked/displace	ed
Grading	
araanig	
^{od} Fair Poor N/A None Observations:	
Description N/A None X V Observations: • There are some low spots along t	
Dd Fair Poor N/A None X A Observations: • There are some low spots along to the spots alon	significant impact on the building, simply
Dd Fair Poor N/A None X Observations: • There are some low spots along t • Lot grading and drainage have a because of the direct and indirect of the direct of the	significant impact on the building, simply damage that moisture can have on the
Dd Fair Poor N/A None X Observations: • There are some low spots along t • Lot grading and drainage have a because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that such as the second s	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted
Determine Fair Poor N/A None X Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading statement	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted
Determine Fair Poor N/A None X Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading statement	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of
d Fair Poor NA None X Observations: • There are some low spots along t • Lot grading and drainage have a because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading s one (1) inch every foot for a distant the building. • With the building. • Observations:	significant impact on the building, simply damage that moisture can have on the ig perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of ce of six (6) feet around the perimeter of
Determine Fair Poor N/A None X Image: N/A Observations: • There are some low spots along to the direct and indirect of because of the direct and indirect of foundation. Recommend monitoring is very important, therefore, that su away from the home. Lot grading sone (1) inch every foot for a distance	significant impact on the building, simply damage that moisture can have on the g perimeter of house for pooling water. It urface runoff water be adequately diverted should slope away and fall a minimum of

Page 8 of 75

3. Vegetation Observations

Good	Fair	Poor	N/A	None	
	Х				

Observations: • Trim trees that are in contact or proximity to home, as branches can abrade roofing or siding.

• Prune or remove any plants or bushes that are in contact or close proximity to home to eliminate pathways of wood destroying insects.

• There are large trees above house. The trees appear healthy at time of inspection. Recommend monitoring for dead branches and trim as necessary.

• Trees within 6 feet foundation. Monitor for potential root damage.



Within 6 feet



Within 6 feet



Contacting roof





Limbs touching roof

4. Patio and Porch Deck

Good	Fair	Poor	N/A	None	. (
					1
X					•


- Observations: • Concrete porch noted at front of house.
- · In satisfactory and functional condition at time of inspection








10. Exterior Faucet Condition











Loose trim



5. Exterior Paint



Observations:

Peeling paint observed, suggest scraping and painting as necessary.
Maintenance tip: All exterior painted wood trim surfaces should be biannually examined and sealed, re-caulked and re-painted as needed.

6. Exterior Caulking



Observations: • Caulking around several windows and doors is beginning to deteriorate. Suggest caulking around windows and doors as necessary.

• Maintenance tip: Exterior caulking should be reviewed on a bi-annual basis and reapplied as necessary.

Roof
1. Roof Condition
Good Fair Poor N/A None X Inspection process: Roof was mounted for inspection Materials: Asphalt shingles noted.
Observations: • Roof appears to be adequately protecting the underlying structure at time of inspection.
 Exposed nails on roofing material. Recommend sealing all fastener heads.
 Some shingles damaged. Due to the conditions of the roof covering, we recommend evaluation by a
<image/>
Exposed nails
Damaged
2. Flashing
Good Fair Poor N/A None X Image: Second and the second at time of inspection. Image: Second at time of inspection.
Maintenance tip: recommend reviewing gaps/pipe boots at through-the-roof projections and sealant around chimney on a bi-annual basis, reseal as necessary.

3. Chimney

Good	Fair	Poor	N/A	Nor
	Х			

Observations:
Some mortar deterioration observed; recommend repair as necessary.
Chimney Crown shows signs of deterioration. Recommend having repaired by a gualified chimney contractor as necessary.



Cracked

Mortar deterioration

4. Vent Caps




Observations: • Vent caps in good condition at time of inspection.

5. Gutter

Good	Fair	Poor	N/A	None	Observations:
	Х				Maintenance Tip: Keep gutters cleared of organic debris to prevent
		2	-		downspouts from being clogged causing overflow at gutters, ensure that all downspouts have extensions/splash blocks to carry water away from the

foundation.

• Downspout drains onto sidewalk / driveway. Recommend exploring ways to divert water away from this area, or at the very least, recognize this as a potential ice hazard; use ice melt products and exercise caution.



Drains to driveway

Main panel: Federal Pacific/missing screws

Your Address Here, Baltimore, MD



Damaged insulation



Aluminum wire



Sub panel: Federal pacific




Aluminum wire



Double tapped





Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1.	Heater	Condition

Good	Fair	Poor	N/A	None	Materials: The heater is located in the basement
					Materials. The heater is located in the basement
	X				Materials: Gas fired forced hot air
					Observations:

• The furnace was operable by normal controls at time of inspection.

• Maintenance tip: Recommend an annual HVAC cleaning/inspection by a licensed professional to assure peak efficiency and extend service life.

Manufacture date: 2009

This report may contain information provided as a courtesy about equipment age. Equipment age interpreted from component labels is deemed reliable, but not guaranteed, and should be confirmed.

• Fuel Furnace: Last service date is over one year ago, or is unable to be determined. There are areas which cannot be seen without specialized equipment and training. One such area is the combustion chamber / heat exchanger where cold air blows across the "fire box", becoming the hot air that circulates throughout your home. During the life span of any furnace, this metal wall may develop a crack or a broken weld, allowing carbon monoxide to circulate throughout the home. This is why furnace specialists recommend a complete inspection annually; recommend having unit inspected by certified HVAC technician.







2. Heater Base

Good	Fair	Poor	N/A	None	Observations:
Х					• The heater base is functional.


3. Enclosure

—					
Good	Fair	Poor	N/A	None	Observations:
	Х				The heater enclosure is functional.
		_	-	-	Condensation leak observed near sump pump. Recommend review for repair as necessary



Condensation leak

4. Venting	
Good Fair Poor N/A None	Observations: • Metal double wall chimney vent pipe noted. • Masonry chimney noted. • No concerns with venting at time of inspection.
5. Gas Valves	
Good Fair Poor N/A None	Observations: • Gas shut off valves were present and appear to be functional at time of inspection.



6. Refrigerant Lines

Good	Fair	Poor	N/A	None	Observations:
Х					• No defects found.

7. AC Compress Condition

Good	Fair	Poor	N/A	None	Compressor Type: electric
					compressor rype, electric
	Х				Location: The compressor is located on the exterior grounds.
					Observations:


- A/C was functional at the time of inspection.
- Manufacture date: 2009

• The typical temperature differential split between supply and return air in an air conditioner of this type is 14-24 degrees F. This system responded and achieved an acceptable differential temperature.

- Annual HVAC service contract is recommended.
- With no recent service records observed, we recommend evaluation and service by a licensed HVAC contractor.







Harrison Home Inspections






11. Thermostats

Good	Fair	Poor	N/A	None
Х				

- Observations:
- Location: dining room
- Functional at the time of inspection.
- Recommend that the client(s) have the homeowner provide the instructions for programming or show the client(s) how to do so.



Departure settings



5. Water Heater Condition
Good Fair Poor N/A None X Heater Type: gas Location: The heater is located in the basement. Observations: • Tank is functional at time of inspection. • Tank is functional at time of inspection. • Manufacture date: 2009 This report may contain information provided as a courtesy about equipment age. Equipment age interpreted from component labels is deemed reliable, but not guaranteed, and should be confirmed. • The water heater has exceeded its designed life expectancy. We make no warranty, guarantee or estimation as to the remaining useful life of this unit. Recommend budgeting for replacement.
6. TPRV
Good Fair Por NA X Image: A construction of the construction
7. Number Of Gallons
X Observations: • 40 gallons
8. Water Temperature
Good Fair Poor N/A None X Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA Image: NA
9. Gas Valve
Good Fair Poor N/A None X In place and appears functional at time of inspection.
Page 27 of 75



10. Plumbing Good Fair Poor



Materials: copper Observations: • No deficiencies observed at the visible portions of the supply piping.



1. Overflow Condition		

Bathrooms

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

1. Locations

Locations: Master bathroom • Upstairs hall bathroom • Main floor bathroom

2. Wall Condition

_	Good	Fair	Poor	N/A	None	Materiale: Drawell wells noted . Well paper finish noted . Painted finish
						Materials. Drywaii walls noted. • Wall paper finish noted. • Fainted finish
	XI					Materials: Drywall walls noted. • Wall paper finish noted. • Painted finish noted.
L						Observations

• Some areas not accessible due to stored personal items.



Master bath







Harrison Home Inspections

Your Address Here, Baltimore, MD



Upstairs hall bath





Main floor bath







Page 30 of 75





3. Ceiling Condition

Good	Fair	Poor	N/A	None
	Х			

Observations:

• Stains observed on ceiling, tested dry at time of inspection. Recommend conferring with seller as to any previous water problems in this area and monitor

• Biological growth present in some areas. Recommend having cleaned and treated as necessary.



Master bath: staining



Upstairs hall bath: biological growth



Biological growth

4. Window Condition

Good	Fair	Poor	N/A	None	Materials: Wood framed double hung window noted.
Х					Observations:


Windows tested and were functional at time of inspection.


5. Electrical


Good	Fair	Poor	N/A	None	Observations:
				• Outlets noted appear to	• Outlets noted appear to have loose contacts. Recommend replacement by
					a licensed electrician.



Main floor bath: loose contacts







Harrison Home Inspections

Master bath: damaged grout	Damaged grout					
17. Bath Tubs Good Fair Poor N/A None X Observations: • Tub in good condition at t	ime of inspection.					
18. Enclosure Good Fair Poor N/A None X Observations: • The shower enclosure is functional at the time of the inspection.						
19. Sinks Good Fair Poor N/A None X Observations: • No deficiencies observed						
 20. Toilets Good Fair Poor N/A None Cbservations: The toilet bowl is loose at floor anchor bolts. The wax ring inside the unit must have a snug, secure fit in order to keep from leaking. Properly resealing and re-securing this unit is suggested to prevent water leakage and damage to the sub-floor area. This type of damage is not always visible or accessible to the inspector at time of inspection. 						



Master bath: loose



Main floor bath: loose




Bedrooms

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

1. Locations


Locations: Master bedroom • Front left bedroom • Rear right bedroom • Rear left bedroom

2. Wall Condition






Master bedroom



Your Address Here, Baltimore, MD



Rear right bedroom



Your Address Here, Baltimore, MD



Front left bedroom




3. Ceiling Condition

Х

Materials: There are drywall ceilings noted.

Page 39 of 75





Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. Wall Condition										
Good	Fair	Poor	N/A	None	Materials: Drawall walls noted . Painted finish noted . Walls are alad in					
					Materials: Drywall walls noted. • Painted finish noted. • Walls are clad in paneling.					
X					paneling.					


paneling. Observations:

· Some areas not accessible due to stored personal items.










Your Address Here, Baltimore, MD



Family room: small crack	Small crack
3. Window Condition Good Fair Poor N/A None X Deservations: • Windows tested and were	ible hung window noted. functional at time of inspection.
4. Electrical	
Good Fair Poor N/A None Observations: X Some outlets not accessible	le due to furniture and or stored personal items. time of inspection. Possible spent bulb. Suggest r operation prior to closing.
Family room: inoperative	Inoperative
5. Doors	
Good Fair Poor N/A None X V Door doesn't close properly	y



Dining room: dragging the floor

6. Ceiling Fans

Good	Fair	Poor	N/A	None	Observations:
X					• Operated normally when tested.

7. Closets

Good	Fair	Poor	N/A	None	Observations:
Х					• The closets are in good condition.

8. Floor Condition


Good	Fair	Poor	N/A	None	
v					Flooring Types: Carpet is noted.
^					

- -. _

9. S	9. Smoke Detectors								
Good	Fair	Poor	N/A	None	Observations:				
	X								
	X				 Observations: Operated when tested MAINTENANCE: Periodic testing to ensure proper Smoke Alarm operation is recommended. Old detectors. Smoke detectors should be replaced every 10 years. Recommend replacing as necessary NOTICE: There are missing CO (Carbon Monoxide) detector(s) noted. The Consumer Product Safety Commission recommends that every residence with fuel-burning (gas) appliances be equipped with a UL Listed CO alarm. CO is colorless and odorless and thus impossible to detect without a proper electronic detector. At a minimum, put an alarm near the sleeping rooms on each level in your home. For the most trouble-free operation, I recommend the plug-in type not the battery operated type with digital readout that tells you the peak CO concentration whenever you push the peak level button. 				



Upstairs hall: old





Laundry room: Interior keyed deadbolt

Patio door: does not latch

12. Screen Doors

Good	Fair	Poor	N/A	None	. (
Х					

Observations:

Screen door was functional at time of inspection.

13. Fireplace

	None	N/A	Poor	Fair	Good
		v			
		^			
U					

Aaterials: Family Room Aaterials: Masonry fireplace noted.

Observations:

• Level II inspection — Fireplace inspections are outside the scope of a normal home inspection as there are many areas that require special equipment to evaluate. The National Fire Protection Association (www.nfpa.org) advises that each chimney receive a Level II inspection each time a residence is sold. Inspection levels are explained at www.csia.org/pressroom/press-inspection-levels-explained.htm. It is also advised that this inspection be conducted by a chimney sweep certified by the Chimney Safety Institute of America (www.csia.org).



Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

1. Wall Condition

Good Fair Poor N/A None

Materials: Painted finish noted.



2. Ceiling Condition

Good	Fair	Poor	N/
Х			

Materials: There are drywall ceilings noted.

3. Window Condition

 Good
 Fair
 Poor
 N/A
 None
 Mat

 X

 <

None

Materials: Wood framed double hung window noted.

Observations:

• Windows tested and were functional at time of inspection.

4. Electrical
Cocd Fair Poor NA None X Image: Some outlets were not accessible due to furniture and or stored personal items in the way. • Some outlets were not accessible due to furniture and or stored personal items in the way. • Hot-neutral reversed (reversed polarity) outlets present. Recommend repair as necessary by a licensed electrician • Mone outlets present. Recommend repair as necessary by a licensed electrician
Hot & neutral reversed/not GFCI protected
5. GFCI Good Fair Poor N/A None X Description Observations: • Recommend upgrading All receptacle to GFCI protection within 6 feet of all potential wet locations. • No GFCI protection present, suggest installing GFCI protected receptacles for safety.
6. Cabinets
Cood Fair Poor N/A None Cabinet doors have broken hinges, consult with seller on repair/replacement options. Cabinet doors have broken hinges, consult with seller on repair/replacement options.
Page 50 of 75

7. Counters
Good Fair Poor N/A None Observations:
 X Laminate tops noted. No concerns with counters at time of inspection.
· · · ·
8. Dishwasher
Good Fair Poor N/A None Observations:
X • Operated and functional at time of inspection.
9. Refrigerator condition
Observations.
X • No concerns at time of inspection
10. Doors
Good Fair Poor N/A None Observations:
X • Door does not latch properly.
Does not latch
11. Garbage Disposal
Good Fair Poor N/A None Observations:
X • Operated - appeared functional at time of inspection.
10 Mierowaya
12. Microwave
Observations.
X • Operated and in working condition.
13. Oven & Range
Good Fair Poor N/A None Observations:
X • Oven: Electric
All heating elements operated when tested.
 SAFETY CONCERN: Free standing range missing anti-tip bracket.

Your Address Here, Baltimore, MD

Harrison Home Inspections

	Wissing anti-tip bracket
14. Sinks	
X None Observations: • No deficiencies observed.	
15. Spray Wand	
Good Fair Poor N/A None X Observations: • The spray wand was operated a	and was functional.
16. Floor Condition	
Good Fair Poor N/A None X A	e noted of inspection.
17. Plumbing	
Good Fair Poor N/A None X Image: Second seco	spection.



Page 53 of 75

5 Electrical	
	<text><text></text></text>
	Loose contacts
6. GFCI Good Fair Poor N/A None C	
	Observations: GFCI in place and operational
7. Doors	
	Observations: Doors were functional at time of inspection.
8. Counters	
X •	Observations: Laminate tops noted. No discrepancies noted.
9. Dryer condition	
	Observations: Dryer is functional at time of inspection.
10. Dryer Vent	
Good Fair Poor N/A None C X I IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Observations: Visible portions of dryer vent appear to be connected properly at time of nspection. The dryer vent has loose exterior cover. Repair as necessary

<image/>
11. Wash Basin
Good Fair Poor N/A None X Image: N/A Image: N/A Image: N/A Image: N/A • No leaks observed from drain lines at time of inspection.
12. Floor Condition
X None Materials: Vinyl squares (tiles) are noted
13. Washing Machine condition
X Deservations: • Washing machine was functional at time of inspection
14. Plumbing
Good Fair Poor N/A None X Observations: • Older style metal traps noted. Buyer is cautioned that these traps can leak at any time due to corrosion.
 Active faucet leak observed. Recommend repair by a licensed plumber

Metal trap

Leak

15. Cabinets
X None Observations: No deficiencies observed.


At	tic
1. Access	
Good Fair Poor N/A None X Observations: • Scuttle Hole located in: fro	nt left bedroom, garage
2. Materials	
Materials: Manufactured Tru	usses • Plywood Sheathing
3. Structure	
	of the attic due to limited access. oted. The area tested dry at time of inspection.
Video	

Garage attic



Staining

Staining



Video Video
4. Ventilation
4. Ventilation Good Fair Poor N/A None Observations:
X • Ridge exhaust venting noted.
Gable louver vents noted.
 Attic fan is inoperable, recommend review for repair.
5. Vent Screens
Good Fair Poor N/A None Observations:
X Vent screens noted as functional.
6. Electrical
Good Fair Poor N/A None Observations:
X Connections made outside of a Junction Box, which is a potential shock or
electrocution hazard.
 Wire ends are outside of a Junction Box, which is a potential shock or
electrocution hazard. Recommend repair by a licensed electrician
 Unprofessional installation of electrical wiring noted in attic. All wiring should be properly secured to the framing.
 Improper wiring observed at time of inspection. Recommend repair by
licensed electrician for repair as necessary.
Page 58 of 75

Your Address Here, Baltimore, MD




Garage attic: exposed wire



Loose box



Loose box



Garage attic: open junction box



Loose box



Main attic: Connection outside junction box/improper wiring

Page 59 of 75



Loose box

7. Attic Plumbing

Good	Fair	Poor	N/A	None	Observatio
X					• Plumbing

ons:

- vent pipe appears functional at time of inspection.
- Copper plumbing vent piping

8. Insulation Condition

Good	Fair	Poor	N/A	None	1 Materials: Loose fill insulation noted. • Fiberglass batts noted.	
					Denthy loculation averages 0 to 4 inches	
X					Depth: Insulation averages 3 to 4 inches.	
		•			Observations:	
					 Insulation loval in the attic is typical for homes this ago 	

Insulation level in the attic is typical for homes this age



Garage
1. Walls
Good Fair Poor N/A None X Observations: • Personal items in garage block complete inspection of all floor, wall and ceiling areas. • Unknown staining observed at time of inspection. Area tested dry. Recommend monitoring • Biological growth observed. Recommend cleaning and treating as necessary
<image/>
<image/>



Biological growth



Biological growth



Unknown staining

2. Floor Condition



Materials: Bare concrete floors noted. Observations: • Flooring is in good condition,

3. Rafters & Ceiling N/A

None

Х



Observations: See main attic section

4. Electrical

Good	d Fair	Poor	N/A	None	Observations:	
X					No concerns noted at time of inspection.	
	-!		!	I	• Some outlets not accessible due to furniture and or stored personal items.	
_					• Some outlets not accessible due to furniture and or stored persona	al items.


5. GFCI Good Fair

Х

Poor	N/A	None	Observations:
			Observations.
			CECL in place and

GFCI in place and operational

6. Window Condition
Good Fair Poor N/A None Materials: Wood framed double hung window noted.
X Observations:
• Windows tested and were functional at time of inspection.
7. Fire Door
Good Fair Poor N/A None Observations:
X • There is no self-closing device on the door from the house leading to the
garage. It is strongly recommended that one be installed in order to protect the residence against garage originated fires.
The door between the garage & house does not appear to be a fire rated
door. This may not have been required when originally built. Fire doors are
fundamental to the integrity of fire barriers which provide resistance to the
spread of fire, smoke, and toxic gasses. This means that should a fire occur in the garage, this door does not afford protection until fire-rescue people
arrive. This door should be replaced with a fire rated door.
8. Garage Door Condition
Good Fair Poor N/A None Materials: Single, insulated steel panel, sectional roll-up door.
X Observations:
• No deficiencies observed.
9. Garage Door Parts
Good Fair Poor N/A None Observations:
X • The garage door is functional.
10. Garage Opener Status
X Functional using normal controls.
11. Garage Door's Reverse Status
Good Fair Poor N/A None Observations:
 X • Eye beam system present and operating. • Garage door pressurized auto-reverse is operable.
12. Cabinets Good Fair Poor N/A None Observationed
X Observations: • Cabinets are not secured to the wall at time of inspection. Recommend
review for repair as necessary



Basement

1. Foundation/Walls



Materials: Unfinished basement


Observations:

• Efflorescence observed; this is a mineral deposit left behind from previous exterior water infiltration.

• There were signs of water penetration at foundation wall. Recommend conferring with seller as to any past moisture problems and have evaluated by a qualified basement waterproofing specialist.







Efflorescence

Your Address Here, Baltimore, MD

Harrison Home Inspections



Efflorescence



Staining





High moisture level







2. Insulation



Observations:

• Perimeter insulation was observed to be missing at one or more locations. Recommend repair/replacement to promote enhanced resistance to heat loss which will increase the efficiency of the home and lower heating costs.

3. Doors								
Good	Fair	Poor	N/A	None	Observations:			
Х					Doors were functional at time of inspection.			

4. Windows

Good	Fair	Poor	N/A	INONE	. N
					יין
X					10
~					- T

Materials: Vinyl framed sliding window noted. Observations:

• Windows tested and were functional at time of inspection.

5. Water Main Shut Off

Good	Fair	Poor	N/A	None
	Х			

Located: basement

Location:

- Water main shut off appears to be in good condition at time of inspection.
- There is corrosion/rust observed at supply plumbing. Recommend evaluation by a licensed plumber before leaks occur.



Corrosion

6. Plumbing

Good	Fair	Poor	N/A	None
	Х			

Materials: Copper • Cast Iron

Observations:

• Inspection of all areas of the drain and supply pipes was not possible due to limited access/finshed walls and ceilings to check for defects such as, but not limited too:leaks, corrosion, improper workmanship, and damage.

• No leaks observed at visible portions at time of inspection.

• Unprofessional repair noted at one or more locations noted, recommend review and repairs by a Qualified Plumber.

• Cast iron drain lines have a life expectancy of 60-75 years. Recommend budgeting for replacement, BEFORE leaks occur.






Cast iron

Unprofessional repair

Upprofessional repairCast iron
<u> </u>
7. Water Pressure
X Normal pressure noted
8. Pressure Regulator
Good Fair Poor N/A None Observations:
X • None visible
• We recommend the installation of a pressure regulator.
9. Basement Electric
Good Fair Poor N/A None Observations:
X Some outlets not accessible due to furniture and or stored personal items.
Connections made outside of a Junction Box, which is a potential shock or
electrocution hazard. Recommend installing proper junction boxes.Improper wiring observed at one or more locations. Recommend review by
a licensed electrician for repair as necessary
Tornection outside junction box/improper wiring
Page 69 of 75
1 490 00 01 70

). GFCI	
iod Fair Poor N/A None	
1. Access ^{Ind Fair Poor N/A None} Materials: Interior stairway noted.	
(Observations:	
• No concerns at time of inspection.	
2. Stairs	
Observations:	
No concerns with stairs at time of inspection.	
3. Railings	
Not Fair Poor N/A None Observations:	
No concerns with railings at time of inspection	
1. Slab Floor	
Pair Poor N/A None Observations:	
• No concerns with visible portions of slab floor at time of inspection.	
	ent
recognition of cracks or settlement in all but the most severe cases. When	nere
carpeting and other floor coverings are installed, the materials and conc	noutid
of the flooring underneath cannot be determined.	
of the flooring underneath cannot be determined.	
of the flooring underneath cannot be determined. 5. Drainage ^{od Fair Poor N/A None} Observations: (
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner.	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	
of the flooring underneath cannot be determined. 5. Drainage Observations: • Drainage appears functional at time of inspection. • The home has a interior drainage system. It is advised to obtain documentation and warranty information from current owner. 6. Sump Pump od Fair Poor N/A None Observations:	



Your Address Here, Baltimore, MD

Harrison Home Inspections





Staining



Biological growth



Not positively anchored



Not positively anchored



• Biological growth observed on ductwork surface in one or more locations. Recommend having areas cleaned and treated as necessary



Biological growth

1. Smoke Detection	 Observations: Operated when tested MAINTENANCE: Periodic testing to ensure proper Smoke <i>A</i> is recommended. Old detectors. Smoke detectors should be replaced every 1 Recommend replacing as necessary NOTICE: There was no visible CO (Carbon Monoxide) dete home. The Consumer Product Safety Commission recommen residence with fuel-burning (gas) appliances be equipped wit CO alarm. CO is colorless and odorless and thus impossible without a proper electronic detector. At a minimum, put an ala sleeping rooms on each level in your home. For the most trou operation, I recommend the plug-in type not the battery ope with digital readout that tells you the peak CO concentration v push the peak level button. 	0 years. ctor(s) in the nds that every h a UL Listed to detect arm near the uble-free erated type

Glossary

Term	Definition
A/C	Abbreviation for air conditioner and air conditioning
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.
TPR Valve	The thermostat in a water heater shuts off the heating source when the set temperature is reached. If the thermostat fails, the water heater could have a continuous rise in temperature and pressure (from expansion of the water). The temperature and pressure could continue to rise until the pressure exceeds the pressure capacity of the tank (300 psi). If this should happen, the super-heated water would boil and expand with explosive force, and the tank would burst. The super-heated water turns to steam and turns the water heater into an unguided missile. To prevent these catastrophic failures, water heaters are required to be protected for both excess temperature and pressure. Usually, the means of protection is a combination temperature- and pressure- relief valve (variously abbreviated as T&P, TPV, TPR, etc.). Most of these devices are set to operate at a water temperature above 200° F and/or a pressure above 150 psi. Do not attempt to test the TPR valve yourself! Most water heating systems should be serviced once a year as a part of an annual preventive maintenance inspection by a professional heating and cooling contractor. From Plumbing: Water Heater TPR Valves